

RESTOTM


BY



BEFORE



AFTER



BEFORE



AFTER



20°	60°	
1.1	9.8	
DOI	Haze	Rspec
2.3	1.7	0.2
BATCH.003	06/11/20 09:15	

20°	60°	
39.7	72.0	
DOI	Haze	Rspec
86.2	10.6	19.3
BATCH.003	06/11/20 16:19	

3 Step Dry Process for the Restoration of Previously and Properly Polished Concrete. Minimizes Impact on Retail Operations.

SPEED

It's fast. An operator can get 5,000+ square feet per night out of each SASE 8K grinder in wide open spaces. Racking or shelving can slow down production and reduce that number. Ability to restore 40,000 to 50,000 square foot stores in four to five nights with two grinders.

NO MESS

Since it's a dry process, there's no slurry to recover or dispose of. The RESTO system produces only a minimal amount of concrete dust, which can be easily captured using smaller highly efficient vacuums like the Bull 300 EBS, offering 99.99% dust extraction. Additionally, there's no need to tape or drape walls and shelving to protect against slurry damage.

IMPACT

Limited impact on retail store operations. Since the system is so clean and so fast, RESTO allows contractors to get in and out of these stores quickly and not interrupt store operations. In some cases making these floors look as good or better than when they were originally polished.

1-800-522-2606

SASECompany.com